

Firmware V1.8 Notes

1. Fixed issue that caused muted output in certain situations
2. Other smaller fixes and optimizations